

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Client: Crawley Industrial Services Ltd

Site: On-site Vans

Location: RX67 OPD

Asset ID: 181248	Description: NEILSON CHARGER	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	------------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	240	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181249	Description: MILWAUKEE CHARGER	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	--------------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	240	V	Information
Neutral Voltage	29/03/2018	9	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181250	Description: REP SAW	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	----------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass

Overall: Pass

Asset ID: 181251	Description: 110V EXT	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	-----------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
IEC Lead Continuity	29/03/2018	0.024	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
IEC Lead Polarity	29/03/2018			Pass

Overall: Pass

Asset ID: 181252	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	----------------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	241	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181253	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	----------------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	242	V	Information

Overall: Pass

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Neutral Voltage	29/03/2018	9	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181254	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	239	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181255	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	240	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181256	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	240	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181257	Description: MILWAUKEE CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	241	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181258	Description: DEWALT CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	242	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181259	Description: DEWALT CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
------------------	-----------------------------	-------------	---	--

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	241	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181260	Description: HILTI DRILL	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 181261	Description: ANGLE GRINDER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 181262	Description: 110V TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Earth Continuity	29/03/2018	0.014	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	243	V	Information
Neutral Voltage	29/03/2018	10	V	Information
PE Conductor Current	29/03/2018	< 0.15	mA	Pass
Overall: Pass				

Asset ID: 181263	Description: 110V EXT	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
IEC Lead Continuity	29/03/2018	0.33	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
IEC Lead Polarity	29/03/2018			Pass
Overall: Pass				

Asset ID: 181290	Description: EXT REEL	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
IEC Lead Continuity	29/03/2018	0.346	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
IEC Lead Polarity	29/03/2018			Pass
Overall: Pass				

Total Tests: 17