

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Client: Crawley Industrial Services Ltd

Site: On-site Vans

Location: RK61 UXW

Asset ID: 181278	Description: EXT LEAD	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	-----------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
IEC Lead Continuity	29/03/2018	0.158	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
IEC Lead Polarity	29/03/2018			Pass
Overall: Pass				

Asset ID: 181279	Description: EXT LEAD	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	-----------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
IEC Lead Continuity	29/03/2018	0.06	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
IEC Lead Polarity	29/03/2018			Pass
Overall: Pass				

Asset ID: 181280	Description: ANGLE GRINDER	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	----------------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 181281	Description: 110V TRANS	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	-------------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Earth Continuity	29/03/2018	0.04	ohm	Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	242	V	Information
Neutral Voltage	29/03/2018	10	V	Information
PE Conductor Current	29/03/2018	< 0.15	mA	Pass
Overall: Pass				

Asset ID: 181282	Description: MILWAUKEE CHARGER	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	--------------------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	243	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181283	Description: MILWAUKEE CHARGER	User: Admin	Test Instrument: Seaward PrimeTest 300 49A-0680
------------------	--------------------------------	-------------	--

Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	243	V	Information
Overall: Pass				

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181284	Description: MAKITA DRILL	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 181285	Description: REP SAW	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 181286	Description: DEWALT CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	241	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181287	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	242	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181288	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	240	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Touch Current	29/03/2018	< 0.07	mA	Pass
Overall: Pass				

Asset ID: 181289	Description: WALKIE TALKIE TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680	
Test Type	Date	Result	Unit	Status
Visual	29/03/2018			Pass
Insulation Resistance	29/03/2018	> 199	MOhm	Pass
Live Voltage	29/03/2018	242	V	Information
Neutral Voltage	29/03/2018	10	V	Information
Overall: Pass				

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 29/03/2018 To: 29/03/2019

Touch Current	29/03/2018	< 0.07	mA	Pass
				Overall: Pass

Total Tests: 12