

# Detailed Latest Test Results



Test Status: All, Test Type: All  
Person: All, Instrument: All  
From: 29/03/2018 To: 29/03/2019

Client: Crawley Industrial Services Ltd

Site: On-site Vans

Location: RF16 EGZ

|                  |                         |             |   |
|------------------|-------------------------|-------------|---|
| Asset ID: 181264 | Description: 110V TRANS | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|-------------------------|-------------|---|

| Test Type             | Date       | Result | Unit | Status      |
|-----------------------|------------|--------|------|-------------|
| Visual                | 29/03/2018 |        |      | Pass        |
| Earth Continuity      | 29/03/2018 | 0.034  | ohm  | Pass        |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass        |
| Live Voltage          | 29/03/2018 | 242    | V    | Information |
| Neutral Voltage       | 29/03/2018 | 10     | V    | Information |
| PE Conductor Current  | 29/03/2018 | < 0.15 | mA   | Pass        |

Overall: Pass

|                  |                      |             |   |
|------------------|----------------------|-------------|---|
| Asset ID: 181265 | Description: REP SAW | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|----------------------|-------------|---|

| Test Type             | Date       | Result | Unit | Status |
|-----------------------|------------|--------|------|--------|
| Visual                | 29/03/2018 |        |      | Pass   |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass   |

Overall: Pass

|                  |                             |             |   |
|------------------|-----------------------------|-------------|---|
| Asset ID: 181266 | Description: MAKITA CHARGER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|-----------------------------|-------------|---|

| Test Type             | Date       | Result | Unit | Status      |
|-----------------------|------------|--------|------|-------------|
| Visual                | 29/03/2018 |        |      | Pass        |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass        |
| Live Voltage          | 29/03/2018 | 240    | V    | Information |
| Neutral Voltage       | 29/03/2018 | 10     | V    | Information |
| Touch Current         | 29/03/2018 | < 0.07 | mA   | Pass        |

Overall: Pass

|                  |                           |             |   |
|------------------|---------------------------|-------------|---|
| Asset ID: 181267 | Description: MAKITA DRILL | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|---------------------------|-------------|---|

| Test Type             | Date       | Result | Unit | Status |
|-----------------------|------------|--------|------|--------|
| Visual                | 29/03/2018 |        |      | Pass   |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass   |

Overall: Pass

|                  |                                  |             |   |
|------------------|----------------------------------|-------------|---|
| Asset ID: 181268 | Description: BOSCH ANGLE GRINDER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|----------------------------------|-------------|---|

| Test Type | Date       | Result | Unit | Status |
|-----------|------------|--------|------|--------|
| Visual    | 29/03/2018 |        |      | Fail   |

Overall: Fail

|                  |                                |             |   |
|------------------|--------------------------------|-------------|---|
| Asset ID: 181269 | Description: PANASONIC CHARGER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|--------------------------------|-------------|---|

| Test Type             | Date       | Result | Unit | Status      |
|-----------------------|------------|--------|------|-------------|
| Visual                | 29/03/2018 |        |      | Pass        |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass        |
| Live Voltage          | 29/03/2018 | 244    | V    | Information |
| Neutral Voltage       | 29/03/2018 | 10     | V    | Information |
| Touch Current         | 29/03/2018 | < 0.07 | mA   | Pass        |

Overall: Pass

|                  |                                  |             |   |
|------------------|----------------------------------|-------------|---|
| Asset ID: 181270 | Description: WALKIE TALKIE TRANS | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |
|------------------|----------------------------------|-------------|---|

# Detailed Latest Test Results



Test Status: All, Test Type: All  
Person: All, Instrument: All  
From: 29/03/2018 To: 29/03/2019

| Test Type             | Date       | Result | Unit | Status      |
|-----------------------|------------|--------|------|-------------|
| Visual                | 29/03/2018 |        |      | Pass        |
| Insulation Resistance | 29/03/2018 | > 199  | MOhm | Pass        |
| Live Voltage          | 29/03/2018 | 242    | V    | Information |
| Neutral Voltage       | 29/03/2018 | 10     | V    | Information |
| Touch Current         | 29/03/2018 | < 0.07 | mA   | Pass        |
| <b>Overall: Pass</b>  |            |        |      |             |

| Asset ID: 181271      | Description: WALKIE TALKIE TRANS | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |             |
|-----------------------|----------------------------------|-------------|---|-------------|
| Test Type             | Date                             | Result      | Unit  | Status      |
| Visual                | 29/03/2018                       |             |   | Pass        |
| Insulation Resistance | 29/03/2018                       | > 199       | MOhm  | Pass        |
| Live Voltage          | 29/03/2018                       | 242         | V   | Information |
| Neutral Voltage       | 29/03/2018                       | 10          | V   | Information |
| Touch Current         | 29/03/2018                       | < 0.07      | mA  | Pass        |
| <b>Overall: Pass</b>  |                                  |             |   |             |

| Asset ID: 181272      | Description: WALKIE TALKIE TRANS | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |             |
|-----------------------|----------------------------------|-------------|---|-------------|
| Test Type             | Date                             | Result      | Unit  | Status      |
| Visual                | 29/03/2018                       |             |   | Pass        |
| Insulation Resistance | 29/03/2018                       | > 199       | MOhm  | Pass        |
| Live Voltage          | 29/03/2018                       | 241         | V   | Information |
| Neutral Voltage       | 29/03/2018                       | 10          | V   | Information |
| Touch Current         | 29/03/2018                       | < 0.07      | mA  | Pass        |
| <b>Overall: Pass</b>  |                                  |             |   |             |

| Asset ID: 181273      | Description: MILWAUKEE CHARGER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |             |
|-----------------------|--------------------------------|-------------|---|-------------|
| Test Type             | Date                           | Result      | Unit  | Status      |
| Visual                | 29/03/2018                     |             |   | Pass        |
| Insulation Resistance | 29/03/2018                     | > 199       | MOhm  | Pass        |
| Live Voltage          | 29/03/2018                     | 241         | V   | Information |
| Neutral Voltage       | 29/03/2018                     | 10          | V   | Information |
| Touch Current         | 29/03/2018                     | < 0.07      | mA  | Pass        |
| <b>Overall: Pass</b>  |                                |             |   |             |

| Asset ID: 181274      | Description: DEWALT CHARGER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |             |
|-----------------------|-----------------------------|-------------|---|-------------|
| Test Type             | Date                        | Result      | Unit  | Status      |
| Visual                | 29/03/2018                  |             |   | Pass        |
| Insulation Resistance | 29/03/2018                  | > 199       | MOhm  | Pass        |
| Live Voltage          | 29/03/2018                  | 241         | V   | Information |
| Neutral Voltage       | 29/03/2018                  | 9           | V   | Information |
| Touch Current         | 29/03/2018                  | < 0.07      | mA  | Pass        |
| <b>Overall: Pass</b>  |                             |             |   |             |

| Asset ID: 181275      | Description: DEWALT CHARGER | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |             |
|-----------------------|-----------------------------|-------------|---|-------------|
| Test Type             | Date                        | Result      | Unit  | Status      |
| Visual                | 29/03/2018                  |             |   | Pass        |
| Insulation Resistance | 29/03/2018                  | > 199       | MOhm  | Pass        |
| Live Voltage          | 29/03/2018                  | 241         | V   | Information |
| Neutral Voltage       | 29/03/2018                  | 10          | V   | Information |
| <b>Overall: Pass</b>  |                             |             |   |             |

# Detailed Latest Test Results



Test Status: All, Test Type: All  
Person: All, Instrument: All  
From: 29/03/2018 To: 29/03/2019

|               |            |        |    |               |
|---------------|------------|--------|----|---------------|
| Touch Current | 29/03/2018 | < 0.07 | mA | Pass          |
|               |            |        |    | Overall: Pass |

| Asset ID: 181276      | Description: EXT REEL | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |               |
|-----------------------|-----------------------|-------------|---|---------------|
| Test Type             | Date                  | Result      | Unit  | Status        |
| Visual                | 29/03/2018            |             |   | Pass          |
| IEC Lead Continuity   | 29/03/2018            | 0.944       | ohm   | Pass          |
| Insulation Resistance | 29/03/2018            | > 199       | MOhm  | Pass          |
| IEC Lead Polarity     | 29/03/2018            |             |   | Pass          |
|                       |                       |             |   | Overall: Pass |

| Asset ID: 181277      | Description: EXT REEL | User: Admin | Test Instrument: SeawardPrimeTest<br>300 49A-0680 |               |
|-----------------------|-----------------------|-------------|---|---------------|
| Test Type             | Date                  | Result      | Unit  | Status        |
| Visual                | 29/03/2018            |             |   | Pass          |
| IEC Lead Continuity   | 29/03/2018            | 0.344       | ohm   | Pass          |
| Insulation Resistance | 29/03/2018            | > 199       | MOhm  | Pass          |
| IEC Lead Polarity     | 29/03/2018            |             |   | Pass          |
|                       |                       |             |   | Overall: Pass |

Total Tests: 14