

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 08/04/2019 To: 08/04/2020

Client: Crawley Industrial Services Ltd

Site: Van Power Tools

Location: WU14 BZC

Asset ID: 192501	Description: 110V EXT LEAD	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	----------------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
IEC Lead Continuity	08/04/2019	0.39	ohm	Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
IEC Lead Polarity	08/04/2019			Pass
Overall: Pass				

Asset ID: 192502	Description: BOSCH DRILL	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	--------------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 192503	Description: DEWALT CHARGER	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	-----------------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Live Voltage	08/04/2019	240	V	Information
Neutral Voltage	08/04/2019	3	V	Information
Touch Current	08/04/2019	0.17	mA	Pass
Overall: Pass				

Asset ID: 192504	Description: REP SAW	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	----------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 192505	Description: NEILSON CHARGER	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	------------------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Live Voltage	08/04/2019	240	V	Information
Neutral Voltage	08/04/2019	4	V	Information
Touch Current	08/04/2019	0.17	mA	Pass
Overall: Pass				

Asset ID: 192506	Description: ANGLE GRINDER	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	----------------------------	-------------------	---

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Overall: Pass				

Asset ID: 192507	Description: DEWALT CHARGER	User: PAUL AYLING	Test Instrument: SeawardPrimeTest 300 49B-0175
------------------	-----------------------------	-------------------	---

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 08/04/2019 To: 08/04/2020

Test Type	Date	Result	Unit	Status
Visual	08/04/2019			Pass
Insulation Resistance	08/04/2019	> 199	MOhm	Pass
Live Voltage	08/04/2019	244	V	Information
Neutral Voltage	08/04/2019	3	V	Information
Touch Current	08/04/2019	0.17	mA	Pass
				Overall: Pass

Total Tests: 7