

Detailed Latest Test Results



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 09/04/2018 To: 09/04/2019

Client: Crawley Industrial Services Ltd

Site: Van Power Tools

Location: WU14 BZC

Asset ID: 181429	Description: NEILSEN TRANS	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	----------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass
Live Voltage	09/04/2018	243	V	Information
Neutral Voltage	09/04/2018	10	V	Information
Touch Current	09/04/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181430	Description: DEWALT CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	-----------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass
Live Voltage	09/04/2018	242	V	Information
Neutral Voltage	09/04/2018	10	V	Information
Touch Current	09/04/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181431	Description: ANGLE GRINDER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	----------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass

Overall: Pass

Asset ID: 181432	Description: BOSCH DRILL	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	--------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass

Overall: Pass

Asset ID: 181433	Description: DEWALT CHARGER	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	-----------------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass
Live Voltage	09/04/2018	240	V	Information
Neutral Voltage	09/04/2018	10	V	Information
Touch Current	09/04/2018	< 0.07	mA	Pass

Overall: Pass

Asset ID: 181434	Description: EXT REEL	User: Admin	Test Instrument: SeawardPrimeTest 300 49A-0680
------------------	-----------------------	-------------	---

Test Type	Date	Result	Unit	Status
Visual	09/04/2018			Pass
IEC Lead Continuity	09/04/2018	0.34	ohm	Pass
Insulation Resistance	09/04/2018	> 199	MOhm	Pass
IEC Lead Polarity	09/04/2018			Pass

Overall: Pass

Total Tests: 6