



STALLION TESTING CO.

A Lifting Advisory & Certification Agency

incorporating Stallion Plant Services

CERTIFICATE of THOROUGH EXAMINATION

Stallion Lifting Equipment

for cranes, appliances and accessories

Stallion Lifelines

Owner or User Crawley Ind Services Ltd Unit 12 Bolney Grange Business Park Stairbridge Lane Burgess Hill West Sussex RH17 5PA	Location of Examination Crawley Industrial Services Ltd Site Bio Products Dagger Lane Radlett Elstree WD6 3BX
---	---

Certificate No: ZA18252

Colour Code:

Examination Date: 21/03/2018

Ref Number:

RMD Spreader Beams

Line No.	Description	ID Nos	SWL	Particulars of Condition
1	Spreader Beam of RMD Soldier setion 225x180mm x 3600mm long. Twenty adjustment holes at 180mm centres along length for 3000 lifting rings Nos FOS4/V235- 1 FOS4/V235-10 FOS4/V235-36 FOS4/V235-49	3026A 3026B	6000kg Four point lift	Working Order; Note 3026A has a slight bend on one sde of section near one end 3926B has slight bend in flange one side of section middle part of spreader

Previous Examination

Repairs Required attention:

Next Examination Date: 20/03/2019

Surveying Engineers signature

Statutory regulations state that a copy of the report must be sent to the HSE when it reveals the item can not be used safely without the risk of a hazard.

Information required on products if exported to USA and Canada

Lifting Operations and Lifting Equipment Regulations 1998, PUWER 1998, Docks Reg. 1988, Health and Safety at Work Act 1974, inc amendments

The equipment has been thoroughly examined as dated, by a competent lifting gear Engineer, employed by Stallion.

Name Printed:

Stuart Laughton

Certificate Number ZA18252

Page 1 of 1

telephone 01444 246662
 fax 01444 248370
 e-mail testing@stallionplant.co.uk
 web www.stalliontesting.co.uk

Stallion Plant Services Ltd
 The Test House
 Ditchling Common Industrial Estate
 Hassocks, Sussex, BN6 8SG

