

# REPORT OF SAFETY INSPECTION

THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998  
THE PROVISION AND USE OF WORK EQUIPMENT REGULATIONS 1998



Name and address of user CLS LTD Bolney Garage 100 RT Bolney	Location of equipment workshop	Inspection No. HSFELS/550/19219
	Description of equipment Counter Balance	
Name and address of inspecting organisation MID SUSSEX FORKLIFT 47 Bolney Garage 100 RT Bolney	Manufacturer HYSTER	Model 550C
	Serial number C002406654Y	Date of manufacture 1978
	Actual capacity 1850 kg @ 500mm load centres	Actual with attachment kg @ mm load centres

After assembly or installation Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	In service (delete as appropriate)		After exceptional circumstances i.e. Accident Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
	6 Months	12 Months <input checked="" type="checkbox"/>	

Refused to inspect (reason) see GN28 para 4  
N/A

Particulars of load test:  
N/A

Particulars of any other test:  
THOROUGH EXAMINATION

Identification of any part found to have a defect which is or could become a danger to persons, and a description of this defect:  
NONE

Particulars of any repair, renewal or alteration required to remedy a defect found to be a danger to persons (Action to take):  
NONE

Timescale for repair, renewal or alteration  
N/A

Identification of any part found to have a defect which is not yet, but could become a danger to persons, and a description of this defect:  
NONE

Particulars of any repair, renewal or alteration required to remedy a defect which is not yet, but could become a danger to persons (Action to take) (State the time by which it could become a danger):  
NONE

Timescale for repair, renewal or alteration  
N/A

Previous examination	Date Hour meter	This examination	Date Hour meter	Next examination due	Date Hour meter
			19-2-19		18-2-20 N/A

I hereby declare that the equipment described in this record was thoroughly examined in accordance with BITA GN28 and: (tick as appropriate)

No faults have been detected

Faults have been detected and the above actions are required within the time limits specified

Should not be used until the above until the above instructions are carried out

Inspector's name and qualifications P. Judd	User's name CLS	Report approved by MID SUSSEX FORKLIFT
Inspector's signature P. Judd	User's signature	Authorised signature
Date 19-2-19	Date 19-2-19	Date 19-2-19

Format approved by the British Industrial Truck Association in accordance with BITA GN28 Telephone 01344 623800 Email bita@pavillion.co.uk