

Lifting Machines and Accessories Report

Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED -
(4) CUSTOMER OWNED EQUIPMENT**



Policy Number: **NV26035452**

Contract
Number:

Report Number: **E32803024552**

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766439 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck, Counterbalanced D004D09208X Hyster S4.50XL 2000 Depot - Tall Mast Fork Truck	4420kg @ 600mm Load Centres, To 5300mm Lift Height	A Long forks; One off auto-locking device not fitted (bolt fitted). Its correct auto-locking device should be fitted within one month. Handbrake inefficient. This defect should be rectified within one month. B Mast secondary chains are not free to articulate. Left hand steering ram seal weeping oil. Oil evident to underside of truck. Its cause should be investigated and rectified with all excess oil removed. C Indicated running time = 3506 hours. The integrity of the blind upper mast chain anchorages must be ensured. Mast side shift hoses outer sheath cracked and should be monitored for deterioration.

The above items were seen
at: (If blank, refer to the
Location details)

Visit made on behalf of:

Client Name

BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER
OWNED EQUIPMENT


Address

JCB CRAWLEY
 UNIT 12 STAIRBRIDGE LANE
 HAYWARDS HEATH
 WEST SUSSEX
 RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
 Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
 Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
 www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

[Print/email friendly page](#)

Lifting Machines and Accessories Report

Lifting Operations & Lifting Equipment Regulations 1998
 Provision & Use of Work Equipment Regulations 1998
Regular Thorough Examination



Policy Number: **NV26035452**

Name of User: **BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT**

Contract Number:
Report Number: **E32803024551**

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766711 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck, Counterbalanced C002A06659Y Hyster S50C 1978 Depot - Red Hyster	1850kg @ 500mm Load Centres, To 5486mm Lift Height	A None B Mast guard not fitted. Left hand front roll cage fixing not fully wound home. Oil evident to underside of truck. Its cause should be investigated and rectified with all excess oil removed. Flashing warning beacon. C Indicated running time = 8290 hours. Vehicle registration Q869 ANJ. We would recommend fitment of an audible reverse warning siren. Should your risk assessment permit, we strongly recommend this be refitted.

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name: **BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT**

Address: **JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB**

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

[Print](#)

[Close](#)

[Print/email friendly page](#)

Lifting Machines and Accessories Report

Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED -
(4) CUSTOMER OWNED EQUIPMENT**

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**



Policy Number: **NV26035452**

Contract
Number:

Report Number: **E32803024555**

Item No.	Description Serial No.	Safe Working Load(s)
----------	---------------------------	-------------------------

Examination Dates: Last Current Next	Make/Model Year of Manufacture Location Examination Scheme Number		A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766714 JIB Unknown 01-Jul-2019 01-Jul-2020	Crane Attachment SLA05-27576JIB (JIB4) Genie SLA-10 Jib Genie SLA-10 Material Lifting Appliance	Not Marked	A None B The safe working load is not marked for all jib positions. No load hook fitted. C None

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name

BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT

Address

JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests

1-Jul-2019


Competent Person
Allianz Engineering

Date of Report

1-Jul-2019

UK Tel: +44 (0) 1428 722407
ROI Tel: +00353 (0) 1 613 4081

Engineer Surveyor


N. Palmer

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
 Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
 Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
 www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print **Close**

[Print/email friendly page](#)

Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998
 Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT**

Policy Number: **NV26035452**

Contract Number:

Location: **JCB CRAWLEY, UNIT 12
 STAIRBRIDGE LANE, HAYWARDS
 HEATH, WEST SUSSEX, RH17 5PB**

Report Number: **E32803024549**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766714 Unknown 01-Jul-2019 01-Jul-2020	Material Lifting Appliance SLA05-27576 (STACKER 1) Genie SLA-10 2005 Depot	454kg @ 46cm to 181kg @ 1.07m	A Winch auto-locking mechanism inoperative. This defect should be rectified immediately. B

		Suspension wire rope crossed on winch drum. C None
--	--	--

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT
Address JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

[Print/email friendly page](#)**Lifting Machines and Accessories Report**Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998**Regular** Thorough ExaminationName of **BRIGGS EQUIPMENT UK LIMITED -**
User: **(4) CUSTOMER OWNED EQUIPMENT**Policy Number: **NV26035452**Contract
Number:Location: **JCB CRAWLEY, UNIT 12**
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PBReport Number: **E32803024550**

Item No.	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766710 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck, Counterbalanced D004D01964T Hyster S4.50XL 1996 Depot - Short Mast	4500kg @ 600mm Load Centres, To 2781mm Lift Height	A None B Mast guard not fitted. Chains devoid of adequate lubrication. Mast carriage guide devoid of lubrication. C Indicated running time = 3749 hours. Left hand steer tyre beginning to delaminate in areas and should be monitored for further deterioration. Should your risk assessment permit, we strongly recommend this be refitted.

The above items were seen
at: (If blank, refer to the
Location details)

Visit made on behalf of:


Client Name

Address BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER
OWNED EQUIPMENT
JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

[Print](#)

[Close](#)

[Print/email friendly page](#)

Lifting Machines and Accessories Report

Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998



Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT**

Policy Number: **NV26035452**

Contract Number:

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**

Report Number: **E32803024553**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
9766712 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck Attachment J31266 (JCB1) JCB 500-4.0 Jib 2000 Depot - Tall Mast Fork Truck	4000kg @ 500mm Load Centres	A None B None C Seen fitted with 8.5 Ton bow shackle APL5-1, and 5.4 Ton Hook APL13-8 YSL.

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name

BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT

Address

JCB CRAWLEY
 UNIT 12 STAIRBRIDGE LANE
 HAYWARDS HEATH
 WEST SUSSEX
 RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
 Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
 Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
 www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

[Print](#) [Close](#)

[Print/email friendly page](#)

Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998
 Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT**

Policy Number: **NV26035452**

Contract Number:

Location: **JCB CRAWLEY, UNIT 12
 STAIRBRIDGE LANE, HAYWARDS
 HEATH, WEST SUSSEX, RH17 5PB**

Report Number: **E32803024554**

Item No.	Description	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified.
Examination Dates: Last Current Next	Serial No. Make/Model Year of Manufacture Location Examination Scheme Number		

			<p>B. Identification of any parts that require rectification</p> <p>C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)</p>
<p>9766713 Unknown 01-Jul-2019 01-Jul-2020</p>	<p>Fork Truck Attachment 55438 (JCB2) Invicta Fork Attachment - Jib 1998 Depot - Short Mast Fork Truck</p>	<p>Illegible</p>	<p>A None</p> <p>B Safe working load chart illegible.</p> <p>C Seen fitted with 6 Ton bow shackle APL4-1, and 7 Ton Hook APL93-1.</p>

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT

Address JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

[Print/email friendly page](#)

Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of **BRIGGS EQUIPMENT UK LIMITED -**
User: **(4) CUSTOMER OWNED EQUIPMENT**

Policy Number: **NV26035452**

Contract
Number:

Report Number: **E32803024556**

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
LT11007 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck Attachment 62318 (FE1) Invicta Forks & Attachments - Extensions 2010 Depot - On Red Hyster 9766711	1000kg @ 915mm Load Centres	A None B None C Item to be added to the Briggs schedule as authorised by David Lepenwell (Managing Director).

The above items were seen
at: (If blank, refer to the
Location details)

Visit made on behalf of:

Client Name

BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER
OWNED EQUIPMENT

Address

JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

[Print/email friendly page](#)

Lifting Machines and Accessories Report

Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **BRIGGS EQUIPMENT UK LIMITED -
(4) CUSTOMER OWNED EQUIPMENT**



Policy Number: **NV26035452**

Contract
Number:

Report Number: **E32803024557**

Location: **JCB CRAWLEY, UNIT 12
STAIRBRIDGE LANE, HAYWARDS
HEATH, WEST SUSSEX, RH17 5PB**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
LT11008 Unknown 01-Jul-2019 01-Jul-2020	Fork Truck Attachment 8374 (JIB 3) Hyster Jib Depot - Red Hyster 9766711	1925kg @ P1 to 1045kg @ P5	A None B None C Seen fitted with 3.25 Ton bow shackle 5/8-1, and Hook BKL-10-8. SWK not marked. The Hook safe working load should be ascertained and clearly marked. Item to be added to the Briggs schedule as authorised by David Lepenwell (Managing Director).

The above items were seen
at: (If blank, refer to the
Location details)

Visit made on behalf of:

Client Name

BRIGGS EQUIPMENT UK LIMITED - (4) CUSTOMER OWNED EQUIPMENT


Address

**JCB CRAWLEY
UNIT 12 STAIRBRIDGE LANE
HAYWARDS HEATH
WEST SUSSEX
RH17 5PB**

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

This is a part reproduction of the original report which may contain other items.

Date of commencement of examination and tests	1-Jul-2019	Competent Person Allianz Engineering
Date of Report	1-Jul-2019	UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081
Engineer Surveyor	 N. Palmer	

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

[Print](#)

[Close](#)

[Print/email friendly page](#)